

# OnForce™ LFT Long Fiber Compounds

Specialty Engineered Materials

TROUBLESHOOTING RECOMMENDATIONS		
Problem	Cause	Solution
<b>Incomplete Fill</b>	Melt and/or mold too cold	<ol style="list-style-type: none"> <li>1. Increase nozzle and barrel temperatures.</li> <li>2. Increase mold temperature.</li> <li>3. Increase injection rate.</li> <li>4. Increase pack and hold pressure.</li> <li>5. Increase nozzle tip diameter.</li> <li>6. Check thermocouples and heater bands.</li> </ol>
	Mold Design	<ol style="list-style-type: none"> <li>1. Enlarge or widen vents and increase number of vents.</li> <li>2. Check that vents are unplugged.</li> <li>3. Check that gates are unplugged.</li> <li>4. Enlarge gates and/or runners.</li> <li>5. Perform short shots to determine fill pattern and verify proper vent location.</li> <li>6. Increase wall thickness to move gas trap to parting line.</li> </ol>
	Shot size	<ol style="list-style-type: none"> <li>1. Increase shot size.</li> <li>2. Increase cushion.</li> </ol>
<b>Brittleness</b>	Low melt temperature	<ol style="list-style-type: none"> <li>1. Increase melt temperature.</li> <li>2. Increase injection rate.</li> <li>3. Measure melt temperature with pyrometer.</li> </ol>
	Degraded/overheated material	<ol style="list-style-type: none"> <li>1. Decrease melt temperature.</li> <li>2. Decrease back pressure.</li> <li>3. Use smaller barrel/excessive residence time.</li> </ol>
	Gate location and/or size	<ol style="list-style-type: none"> <li>1. Relocate gate to nonstress area.</li> <li>2. Increase gate size to allow higher flow rate and lower molded-in stress.</li> </ol>
	Moisture	<ol style="list-style-type: none"> <li>1. Dry material to above conditions.</li> <li>2. Utilize hopper dryers.</li> </ol>
<b>Fibers/Mineral on Surface or Uneven Surface Appearance</b>	Melt temperature too low	<ol style="list-style-type: none"> <li>1. Increase melt temperature.</li> <li>2. Increase mold temperature.</li> <li>3. Increase injection speed.</li> </ol>
	Insufficient packing	<ol style="list-style-type: none"> <li>1. Increase pack and hold pressure and time.</li> <li>2. Increase shot size.</li> </ol>
<b>Sink Marks</b>	Part geometry too thick	<ol style="list-style-type: none"> <li>1. Reduce wall thickness.</li> <li>2. Reduce rib thickness.</li> </ol>
	Melt too hot	<ol style="list-style-type: none"> <li>1. Decrease nozzle and barrel temperatures.</li> <li>2. Decrease mold temperature.</li> </ol>
	Insufficient material volume	<ol style="list-style-type: none"> <li>1. Increase shot size.</li> <li>2. Increase injection rate.</li> <li>3. Increase packing pressure.</li> <li>4. Increase gate size.</li> </ol>
<b>Flash</b>	Injection pressure too high	<ol style="list-style-type: none"> <li>1. Decrease injection pressure.</li> <li>2. Increase clamp pressure.</li> <li>3. Decrease injection rate.</li> <li>4. Increase transfer position.</li> </ol>
	Excess material volume	<ol style="list-style-type: none"> <li>1. Decrease pack pressure.</li> <li>2. Reduce shot size.</li> <li>3. Decrease injection rate.</li> </ol>
	Melt and/or mold too hot	<ol style="list-style-type: none"> <li>1. Decrease nozzle and barrel temperatures.</li> <li>2. Decrease mold temperatures.</li> <li>3. Decrease screw speed.</li> </ol>

## TROUBLESHOOTING RECOMMENDATIONS

Problem	Cause	Solution
<b>Excessive Shrink</b>	Too much orientation	<ol style="list-style-type: none"> <li>1. Increase packing time.</li> <li>2. Increase hold pressure.</li> <li>3. Decrease melt temperature.</li> <li>4. Decrease mold temperature.</li> <li>5. Decrease injection speed.</li> <li>6. Decrease screw rpm.</li> <li>7. Increase venting.</li> <li>8. Increase cooling time.</li> </ol>
<b>Not Enough Shrink</b>	Too little orientation	<ol style="list-style-type: none"> <li>1. Decrease packing pressure.</li> <li>2. Decrease hold pressure.</li> <li>3. Increase melt temperature.</li> <li>4. Increase mold temperature.</li> <li>5. Increase injection speed.</li> <li>6. Increase screw rpm.</li> <li>7. Decrease cooling time.</li> </ol>
<b>Color Streaks</b>	Incomplete color dispersion	<ol style="list-style-type: none"> <li>1. Increase back pressure.</li> <li>2. Verify color concentrate compatibility.</li> <li>3. Decrease rear zone temperature.</li> <li>4. Increase injection rate.</li> <li>5. Check material for moisture.</li> </ol>
<b>Burning</b>	Melt and/or mold too hot	<ol style="list-style-type: none"> <li>1. Decrease nozzle and barrel temperatures.</li> <li>2. Decrease mold temperature.</li> <li>3. Decrease injection rate.</li> <li>4. Check material for moisture</li> </ol>
	Mold design	<ol style="list-style-type: none"> <li>1. Clean, widen and increase number of vents.</li> <li>2. Increase gate size or number of gates.</li> </ol>
<b>Nozzle Drool</b>	Nozzle temperature too hot	<ol style="list-style-type: none"> <li>1. Decrease nozzle temperature.</li> <li>2. Decrease back pressure.</li> <li>3. Increase screw decompression.</li> </ol>
	Incorrect nozzle type	<ol style="list-style-type: none"> <li>1. Use reverse taper nozzle.</li> </ol>
	Moisture	<ol style="list-style-type: none"> <li>1. Dry material prior to molding.</li> <li>2. Use hopper dryers.</li> </ol>
<b>Weld Lines</b>	Melt front temperatures are too low	<ol style="list-style-type: none"> <li>1. Increase pack and hold pressure.</li> <li>2. Increase melt temperature.</li> <li>3. Increase vent width and locations.</li> <li>4. Increase injection rate.</li> <li>5. Increase mold temperature.</li> </ol>
	Mold design	<ol style="list-style-type: none"> <li>1. Decrease injection rate.</li> <li>2. Increase gate size.</li> <li>3. Perform short shots to determine fill pattern and verify proper vent location.</li> <li>4. Add vents and/or false ejector pin.</li> <li>5. Move gate location.</li> </ol>
<b>Sticking in Mold</b>	Cavities are overpacked	<ol style="list-style-type: none"> <li>1. Decrease injection rate and pressure.</li> <li>2. Decrease pack and hold pressure.</li> <li>3. Decrease nozzle and barrel temperatures.</li> <li>4. Decrease mold temperature.</li> <li>5. Increase cooling time.</li> </ol>
	Mold design	<ol style="list-style-type: none"> <li>1. Increase draft angle.</li> </ol>
	Part is too hot	<ol style="list-style-type: none"> <li>1. Decrease nozzle and barrel temperatures.</li> <li>2. Decrease mold temperature.</li> <li>3. Increase cooling time.</li> </ol>

For questions or issues, please call  
Specialty Engineered Materials Technical Support at:  
440.930.1000

**PolyOne**<sup>™</sup>

Beyond Polymers.  
Better Business Solutions.<sup>SM</sup>

[www.polyone.com](http://www.polyone.com)